


01/31/2005

1087489 - R8 SDMS




- Legend**
- 5-Point Composite Sample Area
 - R&R Air Sample Location
 - Former Railroad Spur
 - Site Boundary
 - Concrete Slab
 - Site Features
 - Barrier Applied (No Confirmation Samples Collected)
 - ND - Nondetect
 - TR - <0.2% Libby Amphibole Asbestos by PLM 9002

Figure 1
Utah Power and Light 3rd West Substation
Sample Results as of January 31, 2005
Libby Sister Site
Salt Lake City, UT

CDM

01/31/2005

1087489 - R8 SDMS



- Legend**
- 5-Point Composite Sample Area
 - P1 R&R Air Sample Location
 - Former Railroad Spur
 - Site Boundary
 - Concrete Slab
 - Site Features
 - Barrier Applied (No Confirmation Samples Collected)
 - ND - Nondetect
 - TR - <0.2% Libby Amphibole Asbestos by PLM 9002

Figure 1
Utah Power and Light 3rd West Substation
Sample Results as of January 31, 2005
Libby Sister Site
Salt Lake City, UT

CDM

